



## *UCI Inspection Report*

### **Capital City Nissan**

1980 SW TOPEKA BLVD.  
 TOPEKA, KS 66612  
 (785) 267-6700  
 MASTEROMIXES@GMAIL.COM

**Dillon Percival**  
*Service Consultant*

**D. Odell**  
*Certified Technician*

#### **YOUR VEHICLE**

|                            |                                   |                     |  |
|----------------------------|-----------------------------------|---------------------|--|
| <b>Year</b><br>2007        | <b>Make</b><br>Infiniti           | <b>Model</b><br>G35 | <b>Engine Type</b><br>3.5L V6 DOHC (MFI) |
| <b>Odometer</b><br>123,277 | <b>VIN #</b><br>JNKBV61F97M820059 | <b>License #</b>    | <b>Date</b><br>12/6/2014                 |



# Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ 1. 10/10 PUBLIC AUCTION, ROAD TEST, LOF INNOVATIVE SOLUTIONS CHECK LIGHTS, BLOCK TEST, UNDER HOOD INCLUDE STEERING LINKS, FLUIDS AT LEVEL, FUNCTIONAL INCLUDE HORN, TIRES, SEATBELTS, W/S, PARKING BRAKE, W/WIPERS & WASHERS, HEATER & DEFROSTER (LOCK ACTUATOR)
- ✓ REPLACE LOCK ACTUATOR



## Package Results

### 10/10 PUBLIC AUCTION VEHICLE "SAFETY ITEMS" INSPECTION FORM

| Failed Task                         | Observation | Recommendation  | Done                     |
|-------------------------------------|-------------|---|--------------------------|
| Measure rear brake lining thickness | 1 mm        | Replace rear brake pads and resurface rear brake rotors | <input type="checkbox"/> |

| Passed Task                            | Observation                                  | Recommendation | Done |
|--|--|----------------|------|
| Check engine performance and operation | Engine performing properly                   |                |      |
| Perform battery performance test       | Battery passes performance test              |                |      |
| Measure front brake lining thickness   | 7 mm or greater: Inspect brakes next service |                |      |

| Passed Tasks  |   |  |
|---|---|--|
| ✓ Check windshield and glass for cracks, chips, and pitting             | ✓ Inspect rear-view mirrors (inside and outside)  | ✓ Check all fluid levels and top off including under hood and driveline components |
| ✓ Check hazard light operation  | ✓ Inspect brake light operation   | ✓ Check back-up light operation  |
| ✓ Inspect taillight, turn signal, side marker, and license plate lights | ✓ Inspect fog lights and headlight low and bright beam operation  | ✓ Check SRS and Seatbelts for normal operation                                     |
| ✓ Inspect windshield wiper and washer operation                         | ✓ Check horn operation  | ✓ Inspect heater and defrost operation including all blower motor speeds           |
| ✓ Inspect parking brake adjustment and operation                        | ✓ Check automatic and manual transmission for normal operation and shifting   | ✓ Check engine performance and operation   |
| ✓ Perform battery performance test                                      | ✓ Check drivetrain operation including engine, trans, transfer case, front and rear differentials, axles, and brake operation | ✓ Block test   |
| ✓ Measure front brake lining thickness                                  | ✓ Measure right front tire tread depth  | ✓ Measure Left front tire tread depth  |
| ✓ Check steering gear assembly, pitman, idler, and tie rod ends         | ✓ REFILL OIL AND RECHECK OIL LEVEL  | ✓ Test antifreeze protection   |



## Recommended Services

Our technicians recommend the following services for your vehicle.

| Original Customer Requests   | Status | Cost     | Deferred | Approved |
|--|--------|----------|----------|----------|
| 1. 10/10 PUBLIC AUCTION,ROAD TEST, LOF INNOVATIVE SOLUTIONS CHECK LIGHTS, BLOCK TEST, UNDER HOOD INCLUDE STEERING LINKS, FLUIDS AT LEVEL, FUNCTUNAL INCLUDE HORN,TIRES,SEATBELTS,W/S, PARKING BRAKE,W/WIPERS & WASHERS, HEATER & DEFROSTER |        | \$130.00 |          | X        |
| REPLACE LOCK ACTUATOR (LOCK ACTUATOR)  |        | \$418.67 | X        |          |
| Inspection Recommendations   | Status | Cost     | Deferred | Approved |
| Replace rear brake pads and resurface rear brake rotors (1 mm)   | Fail   | \$139.95 |          | X        |
| Totals, Taxes and Fees   |        | Cost     | Deferred | Approved |
| Estimate Subtotal  |        | \$688.62 | \$418.67 | \$269.95 |
| Shop Supplies  |        |          |          |          |
| Waste and Disposal   |        |          |          |          |
| Tire Excise Tax  |        |          |          |          |
| Sales Tax  |        |          |          |          |
| <b>Estimate Total</b>  |        |          |          |          |