

UCI Inspection Report

Capital City Nissan

1980 SW TOPEKA BLVD. TOPEKA, KS 66612 (785) 267-6700 MASTEROMIXES@GMAIL.COM

Dillon Percival

Service Consultant

S. Newman

Certified Technician

YOUR VEHICLE

Year 2013	<mark>Make</mark> Nissan		<mark>Model</mark> Altima	Engine Type 2.5L 4-cyl DOHC (MFI)
Odom 38,70		VIN : 1N4AL3AP7E	License #	Date 5/14/2014



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ 1. USED CAR INSPECTION W/ LUBE OIL AND FILTER
- ✓ 2. CUSTOMER REQUEST NITROGEN TIRE FILL
- ✓ 3. PER CUSTOMER REQUEST (ORIGINAL REMOTE BUTTON)
- FOUND THE BUTTONS ON ORIGINAL REMOTE WONT UNLOCK CAR WOULD NEED TO REPLACE REMOTE AND PROGRAM
- ✓ 4. R1405 NTB14-027 OCS REPROGRAM RECALL



Package Results

Capital City Nissan of Topeka Full UCI

Cautioned Task	Observation	Recommendation
Inspect air cleaner element	Found air filter dirty	Replace air filter
Measure rear brake lining thickness	5 mm	
Inspect windshield wiper blades	Found windshield wiper blade(s) worn	Replace both windshield wiper blade inserts
Inspect cabin air (HEPA/micro) filter (if equipped)	Found cabin air filter dirty	Replace cabin air filter
Left front tire tread depth	Left front tire tread measures 4/32"	
Right front tire tread depth	Right front tire tread measures 4/32"	
Windshield for cracks, chips and pitting	Found rock chip in windshield	
Inspect overall tire wear and condition	Found tires cupping/chopping	Mount and balance 4 new tires

Passed Task	Observation	Recommendation
Fill windshield washer fluid	Filled to proper level	
Measure front brake lining thickness	7 mm or greater: Inspect brakes next service	
Left rear tire tread depth	Left rear tire tread measures 7/32" or greater: Inspect tire next service	
Right rear tire tread depth	Right rear tire tread measures 7/32" or greater: Inspect tire next service	

Passed Task	Observation	Recommendation
Check and adjust tire pressures	Tire pressure was set to manufacturer specification - Check tire pressures monthly	

Passed Tasks					
Inspect exhaust system for leaks, damage, and loose parts	Inspect for wheel bearing free play	Inspect axles, driveshaft(s) U-joints and CV joints/boots			
Inspect engine mounts	Inspect transmission mounts	Inspect fuel tank, lines, and connections			
Fill windshield washer fluid	Check power steering fluid level and condition	Check engine oil level and condition			
Check engine coolant level and condition	Check brake fluid level and condition	Check transmission fluid level and condition			
Inspect hazard light operation	Inspect brake light operation	Inspect reverse light operation			
Inspect taillight, turn signal, side marker, and license plate lights	Inspect taillight, turn signal, and side marker assemblies for cracks and damage	Inspect headlight low and high beam operation			
Inspect wiper and washer operation	Check horn operation	Inspect heating and air conditioning operation			
Inspect dash and interior lights	Measure front brake lining thickness	Inspect brake system components			
Inspect instrument cluster warning lamps	Perform battery performance test	Inspect battery terminals and cables			
Inspect drive belts	Inspect all hoses and clamps	Inspect steering components			
Inspect front suspension components	Inspect rear suspension components	Inspect engine for oil leaks			
Inspect transmission for leaks	Inspect brake system for leaks	Inspect cooling system for leaks			
Inspect fog/driving lights (if equipped)	Inspect steering system for leaks	Inspect sway bar/stabilizer bar components			
✓ Left rear tire tread depth	✓ Right rear tire tread depth	Check and adjust tire pressures			

Additional Observations	Recommendation		
TIRE NOW ON RIGHT FRONT	REPLACE TIRE FOR NAIL IN SIDEWALL 215-60- 16 MICHELIN PRIMACY MXV4		
ROTATE AND BALANCE TIRE	ROTATE BEST TO FRONT PER REQUEST		

oQ)

Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Declined	Approved
1. USED CAR INSPECTION W/ LUBE OIL AND FILTER			X
2. CUSTOMER REQUEST NITROGEN TIRE FILL			X

Original Customer Requests		Status	Declined	Approved
3. PER CUSTOMER REQUEST				X
FOUND THE BUTTONS ON ORIGINAL REMOTE WONT UNLOCK CAR WOULD NEED TO REPLACE REMOTE AND PROGRAM (ORIGINAL REMOTE BUTTON)				
4. R1405 NTB14-027 OCS REPROGRAM RECALL				X
Inspection & Additional Recommendations	Insp	Status	Declined	Approved
REPLACE TIRE FOR NAIL IN SIDEWALL 215-60-16 MICHELIN PRIMACY MXV4 (TIRE NOW ON RIGHT FRONT)		Fail		X
Replace cabin air filter (Found cabin air filter dirty)	X	Caution		X
Replace both windshield wiper blade inserts (Found windshield wiper blade(s) worn)	X	Caution		X
Mount and balance 4 new tires (Found tires cupping/chopping)	X	Caution	X	
Replace air filter (Found air filter dirty)	X	Caution		X
ROTATE BEST TO FRONT PER REQUEST (ROTATE AND BALANCE TIRE)		Caution		X