



UCI Inspection Report

Capital City Nissan

1980 SW TOPEKA BLVD.
 TOPEKA, KS 66612
 (785) 267-6700
 MASTEROMIXES@GMAIL.COM

Dillon Percival
Service Consultant

J. Mann
Certified Technician

YOUR VEHICLE

Year 2011	Make Nissan	Model Titan	Engine Type 5.6L V8 DOHC (MFI)
Odometer 32,953	VIN # 1N6BA0EC0BN317501	License #	Date 7/3/2014



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ 1. USED CAR INSPECTION W/ LUBE OIL AND FILTER
- ✓ 2. CUSTOMER REQUEST NITROGEN TIRE FILL
- ✓ 3. CUSTOMER REQUESTS REPLACEMENT OF ALL FOUR TIRES



Package Results

Capital City Nissan of Topeka Full UCI

Cautioned Task	Observation	Recommendation
Measure front brake lining thickness	6 mm	
Inspect windshield wiper blades	Found windshield wiper blade(s) worn	Replace both windshield wiper blades
Inspect cabin air (HEPA/micro) filter (if equipped)	Found cabin air filter dirty	
Inspect engine for oil leaks	Found engine oil seep	Replace oil cooler o-ring
Inspect overall tire wear and condition	Based on individually noted tread depts	Mount and balance 4 new tires

Passed Task	Observation	Recommendation
Fill windshield washer fluid	Filled to proper level	
Measure rear brake lining thickness	7 mm or greater: Inspect brakes next service	
Check and adjust tire pressures	Tire pressure was set to manufacturer specification - Check tire pressures monthly	

Passed Tasks

- | | | |
|---|--|---|
| ✓ Inspect exhaust system for leaks, damage, and loose parts | ✓ Inspect for wheel bearing free play | ✓ Inspect axles, driveshaft(s) U-joints and CV joints/boots |
| ✓ Inspect engine mounts | ✓ Inspect transmission mounts | ✓ Inspect fuel tank, lines, and connections |
| ✓ Inspect air cleaner element | ✓ Fill windshield washer fluid | ✓ Check power steering fluid level and condition |
| ✓ Check engine oil level and condition | ✓ Check engine coolant level and condition | ✓ Check brake fluid level and condition |
| ✓ Check transmission fluid level and condition | ✓ Inspect hazard light operation | ✓ Inspect brake light operation |

- ✓ Inspect reverse light operation
- ✓ Inspect headlight low and high beam operation
- ✓ Inspect heating and air conditioning operation
- ✓ Inspect brake system components
- ✓ Inspect battery terminals and cables
- ✓ Inspect steering components
- ✓ Inspect transmission for leaks
- ✓ Inspect steering system for leaks
- ✓ Windshield for cracks, chips and pitting
- ✓ Inspect rear differential fluid level, condition and check for leaks
- ✓ Inspect taillight, turn signal, side marker, and license plate lights
- ✓ Inspect wiper and washer operation
- ✓ Inspect dash and interior lights
- ✓ Inspect instrument cluster warning lamps
- ✓ Inspect drive belts
- ✓ Inspect front suspension components
- ✓ Inspect brake system for leaks
- ✓ Inspect sway bar/stabilizer bar components
- ✓ Check hood struts
- ✓ Inspect transfer case fluid level, condition and check for leaks
- ✓ Inspect taillight, turn signal, and side marker assemblies for cracks and damage
- ✓ Check horn operation
- ✓ Measure rear brake lining thickness
- ✓ Perform battery performance test
- ✓ Inspect all hoses and clamps
- ✓ Inspect rear suspension components
- ✓ Inspect cooling system for leaks
- ✓ Check and adjust tire pressures
- ✓ Inspect front differential fluid level, condition and check for leaks
- ✓ REFILL OIL AND RECHECK OIL LEVEL

Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Declined	Approved
1. USED CAR INSPECTION W/ LUBE OIL AND FILTER			X
2. CUSTOMER REQUEST NITROGEN TIRE FILL			X
3. CUSTOMER REQUESTS REPLACEMENT OF ALL FOUR TIRES			X
Inspection Recommendations	Status	Declined	Approved
Replace oil cooler o-ring (Found engine oil seep)	Caution		X
Replace both windshield wiper blades (Found windshield wiper blade(s) worn)	Caution		X
Mount and balance 4 new tires (Based on individually noted tread depts)	Caution		X