



UCI Inspection Report

Capital City Nissan

1980 SW TOPEKA BLVD.
 TOPEKA, KS 66612
 (785) 267-6700
 MASTEROMIXES@GMAIL.COM

Dillon Percival
Service Consultant

J. Hanson
Certified Technician

YOUR VEHICLE

Year 2008	Make Nissan	Model Altima	Engine Type 2.5L 4-cyl DOHC (MFI)
Odometer 152,261	VIN # 1N4AL21E78C147661	License #	Date 4/30/2015



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ 1. CAMPAIGN NUMBER: PB090 DESCRIPTION: ALTIMA VARISTOR NTB08-095
- ✓ 2. 10/10 PUBLIC AUCTION. ROAD TEST, OIL AND FILTER IHSP, CHECK LIGHTS, PREFORM BLOCK TEST, UNDER HOOD, STEERING LINKS, FLUIDS AT LEVEL, FUNCTIONAL INCLUDE HORN, TIRES, SEAT BELTS, W/S, PARKING BRAKE, WINDSHIELD WIPERS/WASHERS, HEATER AND DEFROSTER.
- ✓ 3. UCD REQUESTS REPLACEMENT OF CVT TRANSMISSION PER PRIOR DIAG OF STALL CONDITION.



Package Results

10/10 PUBLIC AUCTION VEHICLE "SAFETY ITEMS" INSPECTION FORM

Cautioned Task	Observation	Recommendation	Done
Measure rear brake lining thickness	5 mm		
Measure front brake lining thickness	4 mm		
Measure Left front tire tread depth	5/32		

Passed Task	Observation	Recommendation	Done
Check engine performance and operation	Engine performing properly		
Perform battery performance test	Battery passes performance test		

Passed Tasks

✓ Check windshield and glass for cracks, chips, and pitting	✓ Inspect rear-view mirrors (inside and outside)	✓ Check all fluid levels and top off including under hood and driveline components
✓ Check hazard light operation	✓ Inspect brake light operation	✓ Check back-up light operation
✓ Inspect taillight, turn signal, side marker, and license plate lights	✓ Inspect fog lights and headlight low and bright beam operation	✓ Check SRS and Seatbelts for normal operation
✓ Inspect windshield wiper and washer operation	✓ Check horn operation	✓ Inspect heater and defrost operation including all blower motor speeds
✓ Inspect parking brake adjustment and operation	✓ Check automatic and manual transmission for normal operation and shifting	✓ Check engine performance and operation

- ✓ Perform battery performance test
- ✓ Measure left rear tire tread depth
- ✓ Check steering gear assembly, pitman, idler, and tie rod ends

- ✓ Check drivetrain operation including engine, trans, transfer case, front and rear differentials, axles, and brake operation
- ✓ Measure right rear tire tread depth
- ✓ REFILL OIL AND RECHECK OIL LEVEL

- ✓ Block test
- ✓ Measure right front tire tread depth
- ✓ Test antifreeze protection



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Deferred	Approved
1. CAMPAIGN NUMBER: PB090 DESCRIPTION: ALTIMA VARISTOR NTB08-095			X
2. 10/10 PUBLIC AUCTION. ROAD TEST, OIL AND FILTER IHSP, CHECK LIGHTS, PREFORM BLOCK TEST, UNDER HOOD, STEERING LINKS, FLUIDS AT LEVEL, FUNCTIONAL INCLUDE HORN, TIRES, SEAT BELTS, W/S, PARKING BRAKE, WINDSHIELD WIPERS/WASHERS, HEATER AND DEFROSTER.			X
3. UCD REQUESTS REPLACEMENT OF CVT TRANSMISSION PER PRIOR DIAG OF STALL CONDITION.			X